
Updated: September 2017



## **Renovation of Fountains**





## **Details**

Location	Podzamcze, Warsaw, Poland.
Description	Renovation of Multimedia Fountain Park.
Date of project	2010-2011.
Where FRP composites are used and why	Basalt fibre reinforced polymer (BFRP) rebars ROCKBAR were used for paths' repair & arrangement of alleys. Rockbar was used instead of steel rebar in order to increase the service life of the fountain and reduce future maintenance costs. Moreover this construction material is more aesthetic as its application excludes the possibility of corrosion processes.
Type of composite used	BFRP rebars.
Further information	http://galencomposite.com/home/implemented-projects/restructure-of-fountain-park-in-warsaw/